

Utility Conflict Report

OWNER	Utility	CPS	Corridor	WW WHITE
	Contact	JAKE MARTINEZ	ID	114
GENERAL INFO	Utility	ELECTRIC		
	Size and Material	STANDARD POWER POLE, TIMBER		
	Utility Conflict Description	POLE WITHIN PROPOSED SIDEWALK		
	Longitudinal or Crossing	CROSSING		
	Placement Relative to ROW	INSIDE		
LOCATION	Sheet No.	220		
	Station Origin			
	Start Station	682+18.57	End Station	
	Start Offset	29.73	End Offset	
	Latitude	29.426389573	Longitude	-98.405727325000001
SUE	Level of Investigation Req'd	NONE		
	Test Hole No	N/A		
	Test Hole Depth	N/A		
RESOLUTION	Recommended Action	ACCOMMODATE - RELOCATION		
	Estimated Resolution Date			
	Resolution Status	UTILITY COORDINATION IN PROGRESS		
	Comment	INSUFFICIENT CLEARANCE PER PROWAG, 48" CLEARANCE REQUIRED. REMOVE ORIGINAL (BROKEN) TIMBER POLE, RELOCATE CONFLICTING POLE TO ORIGINAL LOCATION.		
Date Collected		8/11/2017 7:37:32 AM	Date Modified	
			11/30/2017 8:04:29 AM	

SITE PHOTOS

