

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	NOGALITO	os	SITE PHOTOS	
OWNER	Contact	NINA BITTL	Æ	ID	3010			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRON					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 1	11+35.17						
	Offset -:	32.7126						
	Latitude +	29.388693						
	Longitude -	98.52211						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Unable to open lid					
Date Collected 7/2/2018 1:35:03 PM Date Modified 8/14/2018 4:38:26 PM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800