

## **Utility Conflict Report**

ER	Jtility SAWS		Corridor	NOGALITOS	SITE		
OWNER	Contact	ANN PECH	IE	ID	3044		
0							
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER METER, STEEL				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
河	Longitudinal or Crossing		CROSSING				
0	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 1	126					
	Station 1	35+02.09					
	Offset -	27.35					
	<b>Latitude</b> +29.393860						
	<b>Longitude</b> -98.51770						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A			Buy III	
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			Control of the Control	
	Estimated Resolution Date					(	
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY				
	Comment		Top of meter t Rubber lid thic Back of curb t Sidewalk widtl Steep sidewal Lower cover 3 adjacent sidev	ckness = 2" o box = 3'-1 h = 8'-0" k cross slop 6-4" due to lo	" oe at box		



**PHOTOS** 





**Date Collected** 7/11/2018 7:52:30 AM **Date Modified** 10/12/2018 3:14:06 PM