

Utility Conflict Report

IER	Utility	SAWS		Corridor	NOGALITO	s _	SITE PHOTOS
OWNER	Contact NINA BITTL		E ID		3077		
0							
	Utility		WATER				
INFO	Size and Material		STANDARD WATER VALVE, CAST IRON			RON	
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE	
GEN	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						
	Station 1	41+56.40					
	Offset 3	31.1081					
	Latitude +	-29.395238					
	Longitude	-98.51616					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/13/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				9-/
	Comment		Top of valve to Lid thickness : Sidewalk widtl Valve to face o	= 5" n = 7'-0"			
	Date Collected 7/11/2018 2:58:33 PM Date Modified 8/14/2018 4:38:26 PM						

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800