



Utility Conflict Report

| | | | | | | |
|-----------------------|------------------------------|--|----------|-----------------------|--------------------|--|
| OWNER | Utility | SAWS | Corridor | RIGSBY | SITE PHOTOS | |
| | Contact | ANN PECHE | ID | 312 | | |
| GENERAL INFO | Utility | WATER | | | |  |
| | Size and Material | STANDARD WATER METER, CAST IRON | | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | CROSSING | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | |
| LOCATION | Sheet No. | 113 | | | |  |
| | Station | 656+37.62 | | | | |
| | Offset | 14.17 | | | | |
| | Latitude | +29.398200 | | | | |
| | Longitude | -98.43443 | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | |
| | Test Hole No | N/A | | | | |
| | Test Hole Depth | N/A | | | | |
| RESOLUTION | Recommended Action | MINIMIZE - PROTECT IN PLACE | | | | |
| | Estimated Resolution Date | | | | | |
| | Resolution Status | UTILITY OWNER INFORMED OF UTILITY | | | | |
| | Comment | Meter within driveway outside accessible route | | | | |
| Date Collected | | Date Modified | | 11/28/2018 6:59:12 AM | | |