

## **Utility Conflict Report**

<b>K</b>	Utility	SAWS		Couridos	SVV MILITAE	ov.	SITE PHOTOS		
N	_			Corridor		X I			
OWNER	Contact	ANN PECH	E	ID	3174				
INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
Z									
\A	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
開									
GENERAL	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	147					CHICAGO		
	Station 6	632+12.12							
	Offset 2	21.3732							
	Latitude -	+29.356429							
	Longitude	-98.52837							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
N O	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Manhole to back of driveway apron = 6'-9"						
			Unable to ope	n manhole					
RESO									
R									
	<b>Date Collected</b> 7/31/2018 3:39:59 PM <b>Date Modified</b> 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800