

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3187			
Ó								
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD WATER VALVE, CAST IRON					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW				Company of the same	
LOCATION	Sheet No.							
	Station							
	Offset							
	<b>Latitude</b> +29.521473					/E TOTAL		
	Longitude -	-98.63848				*		
SUE	Level of Investigation Req'd		NONE			13-		
	Test Hole No		N/A					
	Test Hole Depth		N/A			W 197		
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Bandera edge	of paveme	nt to valve =	8'-9"	The state of the s	
	<b>Date Collected</b> 8/16/2018 10:50:16 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM							