

Utility Conflict Report

| IER | Utility | SAWS | | Corridor | BANDERA | | SITE PHOTOS | |
|------------|--|------------|--|----------|---------|--|--|--|
| OWNER | Contact | ANN PECH | E | ID | 3211 | | | |
| | Utility | | WATER | | | | | |
| INFO | Size and Material | | STANDARD WATER METER, STEEL | | | | | |
| GENERAL I | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | DUTE | | | |
| Ë | Longitudinal or Crossing | | CROSSING | | | | THE RESERVE OF THE PERSON OF T | |
| 0 | Placement Relative to ROW | | INSIDE ROW | | | | 4 | |
| LOCATION | Sheet No. | 316 | | | | | | |
| | Station 1 | 1812+09.50 | | | | | | |
| | Offset - | 44.93 | | | | | | |
| | Latitude - | +29.502107 | | | | | | |
| | Longitude | -98.62611 | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | |
| | Test Hole No | | N/A | | | | | |
| 0, | Test Hole Depth | | N/A | | | | | |
| | Recommended Action | | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | | |
| RESOLUTION | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | | Driveway joint to meter = 5'-1" Unable to open lid | | | | | |
| | Date Collected 8/17/2018 11:24:21 AM Date Modified 12/19/2018 7:58:12 AM | | | | | | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800