

Utility Conflict Report

| ER | Utility | SAWS | | Corridor | BANDERA | SITE PHOTOS | | |
|--|----------------------------------|------------|--|----------|---------|-------------|--|--|
| OWNER | Contact | ANN PECH | E | ID | 3236 | | | |
| 0 | | | | | | | | |
| GENERAL INFO | Utility | | WATER | | | | | |
| | Size and Material | | STANDARD WATER VALVE, CAST IRON | | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | |
| LOCATION | Sheet No. 2 | 297 | | | | | | |
| | Station 1 | 744+38.93 | | | | | | |
| | Offset - | 43.54 | | | | | | |
| | Latitude + | -29.489396 | | | | | | |
| | Longitude . | -98.61085 | | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | |
| | Test Hole No | | N/A | | | | | |
| | Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | MINIMIZE - PROTECT IN PLACE | | | | | |
| | Estimated Resolution Date | | | | | | | |
| | Resolution Status | | UTILITY OWNER INFORMED OF UTILITY | | | | | |
| | Comment | | Top of valve to surface = 1'-8" Lid thickness = 1 1/2" Back of sidewalk to valve = 1'-0" | | | | | |
| Date Collected 8/20/2018 9:25:56 AM Date Modified 12/19/2018 11:48:38 AM | | | | | | | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800