

Utility Conflict Report

ER	Utility	CPS	Corridor	BANDERA	SITE PHOTOS	
OWNER	Contact	BILL FEY	ID	3237		
O						
GENERAL INFO	Utility		GAS			
	Size and Material		STANDARD GAS VALVE, CAST IRON			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE		TE .	
	Longitudinal or Crossing		CROSSING			
	Placement Relativ	ve to ROW	INSIDE ROW			
LOCATION	Sheet No.					
	Station					
	Offset					
	Latitude +29.489307					
	Longitude -98.61075					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT		- * *	
	Estimated Resolution Date		8/28/2018			
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Back of sidewalk to valve = 1'-4" Unable to open lid			
	Date Collected 8/20/2018 10:07:45 AM Date Modified 11/28/2018 6:59:12 AM					