

Utility Conflict Report

| | | | | | |
|-----------------------|-------------------------------------|---|----------------------|---------|-----------------------|
| OWNER | Utility | SAWS | Corridor | BANDERA | SITE PHOTOS |
| | Contact | ANN PECHE | ID | 3241 | |
| GENERAL INFO | Utility | SANITARY SEWER | | | |
| | Size and Material | STANDARD MANHOLE, CAST IRON | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | | | | |
| | Station | | | | |
| | Offset | | | | |
| | Latitude | +29.489185 | | | |
| | Longitude | -98.61064 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | |
| | Estimated Resolution Date | 9/13/2018 | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | |
| | Comment | Face of curb to manhole = 5'-9" Unable to open manhole | | | |
| Date Collected | | 8/20/2018 10:16:53 AM | Date Modified | | 11/28/2018 6:59:12 AM |

