

Utility Conflict Report

ER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3254			
	Utility		WATER					
INFO	Size and Material		STANDARD FIRE HYDRANT					
GENERAL I	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.						THE PARTY OF THE P	
	Station	tation					XINO.	
	Offset							
	Latitude +29.491472							
	Longitude -98.61274							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLIC	CONFLICT				
	Estimated Resolution Date		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Back of sidewalk to hydrant = 1"					
	Date Collected 8/20/2018 11:43:02 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800