

Utility Conflict Report

OWNER	Utility	CPS	Corridor	NOGALITOS	SITE PHOTOS		
	Contact	BILL FEY	ID	4026			
GENERAL INFO	Utility	GAS					
	Size and Material	STANDARD GAS VALVE, CAST IRON					
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing	CROSSING					
	Placement Relative to ROW	INSIDE ROW					
LOCATION	Sheet No.	113					
	Station	111+90.02					
	Offset	29.7					
	Latitude	+29.388631					
	Longitude	-98.52190					
SUE	Level of Investigation Req'd	NONE					
	Test Hole No	N/A					
	Test Hole Depth	N/A					
RESOLUTION	Recommended Action	MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date						
	Resolution Status	UTILITY OWNER INFORMED OF UTILITY					
	Comment	Back of curb to valve = 3'-3" Top of valve to surface = 6.5" Lid thickness = 1.5"					
Date Collected		7/2/2018 2:13:12 PM		Date Modified		10/12/2018 3:14:06 PM	

