

Utility Conflict Report

JER	Utility	SAWS		Corridor	NOGALITOS	SITE P	
OWNER	Contact	ANN PECH	E	ID	4032		
	Utility		SANITARY SEWER				
INFO	Size and Material		STANDARD MANHOLE, CAST IRON			J. J	
GENERAL II	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
Ä	Longitudinal or 0	Crossing	CROSSING				
Θ	Placement Relative to ROW		INSIDE ROW				
OCATION	Sheet No.	115				A	
	Station	114+73.26					
	Offset -	-27.33					
0	Latitude	+29.389375				1	
Ľ	Longitude	-98.52151					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
0,	Test Hole Depth		N/A				
	Recommended Action		MINIMIZE - PI	ROTECT IN	I PLACE		
	Estimated Resolution Date						
RESOLUTION	Resolution Status		UTILITY OWN	IER INFOR	FORMED OF UTILITY		
	Comment		Lid thickness: Bottom of con Width of sidew Rim is on an e to sidewalk, lo sidewalk impre	e to top of l valk = 6.5' existing ram wer rim 1" a	Mos		
	Data Collected 7/2/2018 3:21:17 DM Data Modified 10/12/2018 3:14:06 D						

SITE PHOTOS





