

Utility Conflict Report

OWNER	Utility	ility SAWS		Corridor	NOGALITOS)S	SITE PHOTOS	
	Contact ANN PECHI				4040			
Ō							TOO	
GENERAL INFO	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON			8		
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			OUTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 116							
	Station 1	16+73.53						
	Offset -27.64							
	Latitude +29.389831							
	Longitude	-98.52113						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A				e .	
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ILITY		
	Comment		Lid thickness = 1.5" Bottom of cone to surface = 12" Bottom of cone to lid lip = 10.5" Pole to manhole = 2'-5" Lower rim 5" (existing rings = 8")					
	Date Collected 7/3/2018 8:05:28 AM Date Modified 10/12/2018 3:14:06 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800