

Utility Conflict Report

ER	Utility	SAWS		Corridor	NOGALITOS		SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	4044				
GENERAL INFO	Utility		WATER				Volley And		
	Size and Material		STANDARD FIRE HYDRANT						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			E			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	neet No. 117					Way a little with		
	Station	118+23.88					Caller		
	Offset -	Offset -27.09							
	Latitude +29.390103								
	Longitude	-98.52080							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			TY			
	Comment		Sidewalk width = 6'-4" Fire hydrant to face of wall = 2'-2" Fire hydrant to back of curb = 3'-4" Evidence of overtracking						
	Date Collected 7/3/2018 8:25:53 AM Date Modified 10/12/2018 3:14:06 PM								