

Utility Conflict Report

IER	Utility	CPS		Corridor	NOGALITO	os	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	4050			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	76						
	Station	118+72.29						
	Offset	22.58					W 3 1 19 2 1	
	Latitude	+29.390186						
	Longitude	-98.52054					2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ILITY		
	Comment		Pole marking: R14010 Pole to back of sidewalk = 3'-6" Pole to fence = 4'-6" CATV cable					
	Date Collected 7/10/2018 8:10:33 AM Date Modified 9/13/2018 2:01:25 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800