

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	NOGALITO	)S	SITE PHOTOS		
OWNER	Contact	JAKE MAR	ΓINEZ	ID	4052				
GENERAL INFO	Utility		ELECTRIC						
	Size and Material		STANDARD POWER POLE, TIMBER						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION		77							
	Station 1	119+79.44							
	Offset 2	24.65							
	Latitude -	+29.390386							
	Longitude	-98.52036					The second section of the section of the second section of the second section of the second section of the section of the second section of the sectio		
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
NOLLION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	<b>Estimated Resolution Date</b>								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
	Comment		Pole ID: R14011						
			Pole to back of curb = 3'-0"						
RESOL									
R									
	Date Collected 7/10/2018 8:25:28 AM Date Modified 9/13/2018 2:01:26 PM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800