

## **Utility Conflict Report**

OWNER	Utility	Utility SAWS		Corridor	NOGALITO	os	SITE PHOTOS
N N	Contact NINA BITTL				4061		SPECIAL AY LITTO 2
Ō						5 58 0 6	
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD FIRE HYDRANT				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE		JTE		
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				1
LOCATION	Sheet No.						
	Station 1	121+79.59					
	Offset -	27.8224					
	<b>Latitude</b> +29.390992						The state of the s
	Longitude	-98.52012					The state of the s
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	<b>Estimated Resolution Date</b>		8/13/2018				LUNCH SPECIA EVER YDAY 11 TO
	Resolution Status		NO RESOLUTION WAS REQUIRED				CANOZ N 33
	Comment		Hydrant to back of sidewalk = 4'-6" Hydrant to back of curb = 2'-4" Sidewalk width = 7'-4"				
	Date Collected         7/10/2018 9:20:48 AM         Date Modified         8/14/201						018 4:38:26 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800