

Utility Conflict Report

OWNER	Utility	SAWS		Corridor ID	SW MILITA 4092	λRY	SITE PHOTOS		
	Contact	ANN PECH	E				plus		
0							art of		
GENERAL INFO	Utility		WATER				Is diel.		
	Size and Material		STANDARD FIRE HYDRANT						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.						No. of the second		
	Station 5	533+87.13							
	Offset	17.5497							
	Latitude -	+29.358134							
	Longitude	-98.55913							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		8/14/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Back of curb to hydrant = 4'-5"						
			Sidewalk width = 6'-0"						
Date Collected 7/23/2018 9:13:41 AM Date Modified 11/28/2018							018 6:59:12 AM		

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800