

## **Utility Conflict Report**

OWNER	Utility	CPS		Corridor ID	SW MILITA 4108	.RY	SITE PHOTOS	
	Contact	JAKE MAR	INEZ					
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER				200	
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE		JTE			
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	130						
	Station 5	540+85.00						
	Offset	15.999						
	Latitude -	+29.357954						
	Longitude	-98.55696						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT			9 2 2 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Fence to pole Back of curb to	Pole marking: 3508 Fence to pole = 5'-11" Back of curb to pole = 2'-9" Back of curb to fence = 9'-6" Adjacent to existing VIA bus stop CATV cable				
	Date Collected	018 6:59:12 AM						

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800