

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	4114	
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC			
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	136			
	<b>Station</b>	557+30.23			
	<b>Offset</b>	15.6744			
	<b>Latitude</b>	+29.357427			
	<b>Longitude</b>	-98.55184			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	Pole ID = LW52030; 434796 Pole to back of curb = 3'-0" Pole to steel fence = 6'-0" Back of curb to fence = 10'-0" CATV cable			
<b>Date Collected</b>		7/27/2018 8:38 AM		<b>Date Modified</b> 11/28/2018 6:59:12 AM	

