

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>		
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	4122			
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC					
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER					
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE					
	<b>Longitudinal or Crossing</b>	CROSSING					
	<b>Placement Relative to ROW</b>	INSIDE ROW					
<b>LOCATION</b>	<b>Sheet No.</b>	138					
	<b>Station</b>	563+83.30					
	<b>Offset</b>	14.7346					
	<b>Latitude</b>	+29.357243					
	<b>Longitude</b>	-98.54975					
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE					
	<b>Test Hole No</b>	N/A					
	<b>Test Hole Depth</b>	N/A					
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT					
	<b>Estimated Resolution Date</b>						
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED					
	<b>Comment</b>	Pole ID: 512471 Pole to back of curb inlet = 1'-2" Pole to back of curb = 2'-0" Pole to front of sidewalk = 2'-8" Sidewalk width = 5'-1" Back of curb to front of sidewalk = 6'-0" Adjacent to VIA temporary bus stop CATV cable					
<b>Date Collected</b>		7/27/2018 9:55:20 AM		<b>Date Modified</b>		11/28/2018 6:59:12 AM	

