

Utility Conflict Report

_								
ER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS		
OWNER	Contact	JAKE MAR	TINEZ	ID	4125			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	140				4/4/		
	Station 5	564+54.20						
	Offset 1	5.7835						
	Latitude +	-29.357126						
	Longitude -98.54952					(SYRIDER)		
SUE	Level of Investigation Req'd		NONE			CONTROL OF THE PROPERTY OF THE		
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Sidewalk widtl	f curb = 3'-' le to back on n = 6'-1" ghway depa	1 1/2" If sidewalk = 1'-10" artment surveying			
	5 . 6 !! !	7/07/0040 4/	2 40 40 414		40/40/0	2040 4 00 04 DM		







12/18/2018 4:00:21 PM **Date Collected** 7/27/2018 10:19:49 AM **Date Modified**