

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOT
×	Contact	ANN PECH	E ID	ID	4141		
0							
GENERAL INFO	Utility		WATER				
	Size and Material		STANDARD WATER VALVE, CAST IRON			RON	JE A
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUT			OUTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				* 5
LOCATION	Sheet No.	155					THATBE
	Station 6	671+03.34					
	Offset	14.78					
	Latitude -	+29.356539					7/1
	Longitude	-98.51625					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						A shared to the state of the st
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Lid flange thic Total lid thickr	valve to surface = 2'-1" ge thickness = 1/2" I thickness = 3 1/2" b back of sidewalk = 5'-6"			
Date Collected 8/1/2018 10:27:36 AM Date Modified 12/18/2018 4:23:37 PI							2018 4:23:37 PM