

## **Utility Conflict Report**

IER	Utility	SAWS		Corridor	SW MILITA	.RY	SITE PHOTOS	
OWNER	Contact ANN PECHI		E ID		4218		101	
	Utility		WATER					
INFO	Size and Material		STANDARD WATER METER, CAST IRON					
GENERAL	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE					
GEN	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 166							
	Station 7	22+07.82						
	Offset 1	9.8059						
	Latitude +	tude +29.356592						
	Longitude	-98.50013						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date						A THE REAL PROPERTY.	
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		No meter foun Lid flange thic Overall lid thic	Meter filled with dirt and water  No meter found in meter box  Lid flange thickness = 1/4"  Overall lid thickness = 2 1/4"  Edge of driveway apron to meter = 5"				
	<b>Date Collected</b> 8/7/2018 9:08:12 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800