

## **Utility Conflict Report**

IER.	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ <b>ID</b>	ID	4219	Carlo Maria	
GENERAL INFO	Utility		ELECTRIC			+	
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	166					
	Station	722+92.97					
	Offset	15.59					
	<b>Latitude</b> +29.356539						
	<b>Longitude</b> -98.49988						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT			116536	
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: LW 3 Back of curb to Sidewalk widtl Back of sidew	o pole = 3'-3 n = 6'-10"	3"		

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:02:48 PM

**Date Modified** 

**Date Collected** 

8/7/2018 9:12:47 AM