

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	SW MILITARY	<b>SITE PHOTOS</b>	
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	4222		
<b>GENERAL INFO</b>	<b>Utility</b>	GAS				
	<b>Size and Material</b>	STANDARD GAS VALVE, CAST IRON				
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE				
	<b>Longitudinal or Crossing</b>	CROSSING				
	<b>Placement Relative to ROW</b>	INSIDE ROW				
<b>LOCATION</b>	<b>Sheet No.</b>	168				
	<b>Station</b>	724+79.93				
	<b>Offset</b>	17.4589				
	<b>Latitude</b>	+29.356595				
	<b>Longitude</b>	-98.49927				
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE				
	<b>Test Hole No</b>	N/A				
	<b>Test Hole Depth</b>	N/A				
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT				
	<b>Estimated Resolution Date</b>					
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED				
	<b>Comment</b>	Top of valve to surface = 11" Lid flange thickness = 1 5/8" Overall lid thickness = 5" Valve adjacent to face of wall Sidewalk width = 6'-2" Back of curb to valve = 5'-8"				
	<b>Date Collected</b>	8/7/2018 9:32:26 AM	<b>Date Modified</b>	11/28/2018 6:59:12 AM		

