

Utility Conflict Report

2	Utility	SAWS		Corridor	SW MILITAR	V	SITE PHOTOS		
Z	-		_			, I			
OWNER	Contact	ANN PECH	E	ID	4592				
GENERAL INFO	Utility		SANITARY SEWER			CQUINTA INTERSEMENT			
	Size and Material		STANDARD MANHOLE, CAST IRON						
	GIZG and Material		STANDARD MANIFOLE, CAST INCIN			-			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			of songer hadas			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.								
	Station 6	644+54.31					Name of the second seco		
	Offset 2	21.0542							
	Latitude -	+29.356522							
	Longitude -	-98.524457							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
NOI	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
	Comment								
000									
RESOLL									
"									
Date Collected 12/17/2018 12:03:37 PM Date Modified 12/17/2018 12:07:03 PM									