

Utility Conflict Report

_								
IER	Utility	SAWS		Corridor	SW MILITA	.RY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	4598			
GENERAL INFO	Utility		WATER			THE REAL PROPERTY AND ADDRESS OF THE PARTY AND		
	Size and Material		STANDARD WATER VALVE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			400 212221 GERMES COOR CONTROL DESCRICT		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	148						
	Station 6	667+21.28					HILLOW AND THE STATE OF THE STA	
	Offset	17.89						
	Latitude -	+29.356538						
Ľ	Longitude -	98.517339						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment							
	Date Collected 12/17/2018 1:59:35 PM Date Modified 12/17/2018 2:40:40 PM							