

## **Utility Conflict Report**

<b>K</b>	Utility	SAWS		Corridor	SW MILITA	DV	SITE PHOTOS		
Į	_		_			ΙΧΊ			
OWNER	Contact	ANN PECH	E	ID	4600				
INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
GENERAL II	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
川川	Longitudinal or Crossing		CROSSING						
0	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	158							
	Station 6	88+15.95							
	Offset	14.89							
	Latitude -	+29.356554							
	Longitude -	98.510774							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
N	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
TION	Comment								
RESOLI									
2									
	Date Collected 12/17/2018 3:01:30 PM Date Modified 12/17/2018 3:04:11 PM								