

Utility Conflict Report

_								
JER	Utility	SAWS		Corridor	SW MILITAI	RY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	4604			
GENERAL INFO	Utility		WATER			ISI SANANTONO		
	Size and Material		STANDARD WATER VALVE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			ACCUMUNATE CONTROL CON		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	194						
	Station 8	352+86.68					CASH LUARS - \$55,000	
	Offset -	24.87						
00	Latitude +	-29.356857						
Ľ	Longitude	-98.53119						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment							
	Date Collected 12/18/2018 7:26:36 AM Date Modified 12/18/2018 7:27:30 AM							