

## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	SAWS	<b>Corridor</b>	MILITARY	<b>SITE PHOTOS</b>
	<b>Contact</b>	ANN PECHE	<b>ID</b>	4608	
<b>GENERAL INFO</b>	<b>Utility</b>	SANITARY SEWER			
	<b>Size and Material</b>	STANDARD MANHOLE, CAST IRON			
	<b>Accessible Route</b>	ASSET IS INSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	95			
	<b>Station</b>	1254+57.67			
	<b>Offset</b>	-34.85			
	<b>Latitude</b>	+29.353992			
	<b>Longitude</b>	-98.424181			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	MINIMIZE - PROTECT IN PLACE			
	<b>Estimated Resolution Date</b>				
	<b>Resolution Status</b>	UTILITY OWNER INFORMED OF UTILITY			
	<b>Comment</b>	Manhole within sidewalk accessible route			
<b>Date Collected</b>		12/18/2018 8:55:12 AM	<b>Date Modified</b>		12/18/2018 9:20:06 AM

