


## Utility Conflict Report

<b>OWNER</b>	<b>Utility</b>	CPS	<b>Corridor</b>	MILITARY	<b>SITE PHOTOS</b> 
	<b>Contact</b>	JAKE MARTINEZ	<b>ID</b>	7012	
<b>GENERAL INFO</b>	<b>Utility</b>	ELECTRIC			
	<b>Size and Material</b>	STANDARD POWER POLE, TIMBER			
	<b>Accessible Route</b>	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	<b>Longitudinal or Crossing</b>	CROSSING			
	<b>Placement Relative to ROW</b>	INSIDE ROW			
<b>LOCATION</b>	<b>Sheet No.</b>	227			
	<b>Station</b>	1092+05.51			
	<b>Offset</b>	31.6202			
	<b>Latitude</b>	+29.353450			
	<b>Longitude</b>	-98.42472			
<b>SUE</b>	<b>Level of Investigation Req'd</b>	NONE			
	<b>Test Hole No</b>	N/A			
	<b>Test Hole Depth</b>	N/A			
<b>RESOLUTION</b>	<b>Recommended Action</b>	NO CONFLICT			
	<b>Estimated Resolution Date</b>	8/13/2018			
	<b>Resolution Status</b>	NO RESOLUTION WAS REQUIRED			
	<b>Comment</b>	Pole to front of sidewalk = 3'-2" Back of curb to pole = 2'-6" Sufficient vertical clearance			
<b>Date Collected</b>		8/2/2018 11:01:14 AM		<b>Date Modified</b>	11/28/2018 6:59:12 AM

