

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor	SW MILITAI	RY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E <b>ID</b>	ID	7038			
GENERAL INFO	Utility		WATER					
	Size and Material		STANDARD FIRE HYDRANT					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		OUTE			
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 211							
	Station 9	45+52.77						
	Offset -2							
	Latitude +							
	Longitude -98.50215							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Hydrant adjacent to back of sidewalk					
<b>Date Collected</b> 8/3/2018 8:48:39 AM <b>Date Modified</b> 11/28/2018 6:59:12 AM								