

Utility Conflict Report

| ER | Utility | SAWS | | Corridor | SW MILITARY | SITE PHOTOS | |
|--|--|------------------------------|---|----------|-------------|--|-----------|
| OWNER | Contact | ANN PECH | E | ID | 7090 | Anna Carlo | |
| GENERAL INFO | Utility | | SANITARY SEWER | | | | |
| | Size and Material | | SANITARY SEWER CLEANOUT | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | The state of the s | |
| LOCATION | Sheet No. 1 | 197 | | | | | |
| | Station 8 | 380+57.94 | | | | | |
| | Offset -20.7438 Latitude +29.356857 | | | | | | |
| | | | | | | | Longitude |
| | SUE | Level of Investigation Req'd | | NONE | | | |
| Test Hole No | | N/A | | | | | |
| Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | MINIMIZE - PROTECT IN PLACE | | | | |
| | Estimated Resolution Date | | | | | PAWW Reksmill | |
| | Resolution Status | | UTILITY OWNER INFORMED OF UTILITY | | | | |
| | Comment | | Cleanout filled with water Cleanout adjacent to back of concrete driveway apron | | | | |
| Date Collected 8/3/2018 2:47:39 PM Date Modified 12/18/2018 8:41:48 AM | | | | | | | |