

Utility Conflict Report

ER	Utility	CPS	Corrido	or SW MILITA	ARY	SITE PHOTOS	
OWNER	Contact	BILL FEY	ID				
O	Contact	DILL FET	U	7105			
GENERAL INFO	Utility		GAS				
	Size and Material		STANDARD GAS VALVE, CAST IRON				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
川川	Longitudinal or Crossing		CROSSING				
0	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	194					
	Station	852+71.84					
	Offset	-25.86					
	Latitude	+29.356732					
	Longitude	-98.53109					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A			A	
0)	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			Note that the state of the stat	
	Estimated Resolution Date						
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY Unable to open lid Valve adjacent to back of concrete driveway apron				
	Comment						
	Date Collected 8/3/2018 4:11:32 PM Date Modified 11/28/2018 6:59:12 AM						