

Utility Conflict Report

| | | | | | | | |
|-----------------------|-------------------------------------|--|-----------------|----------------------|--------------------|-----------------------|--|
| OWNER | Utility | SAWS | Corridor | SW MILITARY | SITE PHOTOS | | |
| | Contact | ANN PECHE | ID | 7114 | | | |
| GENERAL INFO | Utility | SANITARY SEWER | | | | | |
| | Size and Material | STANDARD MANHOLE, CAST IRON | | | | | |
| | Accessible Route | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | CROSSING | | | | | |
| | Placement Relative to ROW | INSIDE ROW | | | | | |
| LOCATION | Sheet No. | 188 | | | | | |
| | Station | 788+31.75 | | | | | |
| | Offset | -17.8186 | | | | | |
| | Latitude | +29.357697 | | | | | |
| | Longitude | -98.55147 | | | | | |
| SUE | Level of Investigation Req'd | NONE | | | | | |
| | Test Hole No | N/A | | | | | |
| | Test Hole Depth | N/A | | | | | |
| RESOLUTION | Recommended Action | MINIMIZE - PROTECT IN PLACE | | | | | |
| | Estimated Resolution Date | | | | | | |
| | Resolution Status | UTILITY OWNER INFORMED OF UTILITY | | | | | |
| | Comment | Bottom of cone to surface = 1'-0" Bottom of cone to bottom of ring = 5" Manhole to fence = 4'-7" | | | | | |
| | | | | | | | |
| Date Collected | | 8/6/2018 9:23:55 AM | | Date Modified | | 12/18/2018 7:21:30 AM | |

