PAPE-DAWSON ENGINEERS

Utility Conflict Report

OWNER

Utility	AT&T	**Corridor**	BANDERA
Contact	PHILIP AUSTIN	**ID**	3207

GENERAL INFO

Utility	COMMUNICATIONS
Size and Material	STANDARD MANHOLE, CAST IRON
Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE
Longitudinal or Crossing	CROSSING
Placement Relative to ROW	INSIDE ROW

LOCATION

Sheet No.	
Station	
Offset	
Latitude	+29.502318
Longitude	-98.62625

SUE

Level of Investigation Req'd	NONE
Test Hole No	N/A
Test Hole Depth	N/A

RESOLUTION

Recommended Action	NO CONFLICT
Estimated Resolution Date	
Resolution Status	NO RESOLUTION WAS REQUIRED
Comment	Unable to open manhole

SITE PHOTOS

Date Collected	8/17/2018 10:57:25 AM	**Date Modified**	11/28/2018 6:59:12 AM