

Utility Conflict Report

ER	Utility	CPS		Corridor	US 90		SITE PHOTOS		
OWNER	Contact	JAKE MAR	ΓINEZ	ID	101				
GENERAL INFO	Utility		ELECTRIC			MARCHINE RES			
	Size and Material		UNKNOWN						
	Utility Conflict Description		UNDERGROUND ELECTRIC LINES RUNNING PERPENDICULAR TO PROPOSED SIDEWALK						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE						
LOCATION	Sheet No.	161							
	Station Origin						The second		
	Start Station	312+37.27	End Station						
	Start Offset	15.50	End Offset						
	Latitude	29.398960101	Longitude	-98.6412858	308999996				
SUE	Level of Investigation Req'd		QLA						
	Test Hole No								
	Test Hole Dept	th					Mary San Control		
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Res	olution Date							
	Resolution Status		UTILITY COORDINATION IN PROGRESS						
	Comment		DEPTH AND NUMBER OF UNDERGROUND ELECTRIC LINES UNKNOWN, POTENTIAL VERTICAL CONFLICT WITH PROPOSED SIDEWALK. LOCATION TO BE POTHOLED.			Ussa			
Date Collected 8/23/2017 9:50:49 AM Date Modified 11/29/2017 10:00:11 AM									

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800