

Utility Conflict Report

VER	Utility	CPS		Corridor	SAN PEDRO	SITE PHOTOS	
OWNER	Contact	JAKE MAR	ΓINEZ	ID	107		
	Utility		ELECTRIC			PROTEINER SCOR	
INFO	Size and Material		STANDARD LUMINAIRE				
GENERAL	Utility Conflict Description		LUMINAIRE LOCATED WITHIN PROPOSED PAVEMENT				
GEN	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE				
LOCATION	Sheet No.	153]	
	Station Origin						
	Start Station	608+48.40	End Station			HERETHINE BALLAN HUNGERAN KANNEN	
	Start Offset	-38.6	End Offset				
	Latitude	29.518674270	Longitude	-98.4994270	91000001		
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A			A CONTRACTOR OF THE PARTY OF TH	
	Test Hole Depth		N/A			_	
	Recommended Action		ACCOMODATE - RELOCATION				
RESOLUTION	Estimated Resolution Date						
	Resolution Status		UTILITY COORDINATION IN PROGRESS				
	Comment		RELOCATE LUMINAIRE OUTSIDE PROPOSED PAVEMENT AND SIDEWALK				
	Date Collected	9/20/2017 2:	42:13 PM	Date M	odified 11/30	0/2017 8:10:03 AM	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800