

Utility Conflict Report

ER	Utility	TIME WARI	NER	Corridor	RIGSBY	SITE PHOTOS		
OWNER	Contact	FRANK CYPF	RIAN	ID	241			
GENERAL INFO	Utility		COMMUNICATIONS					
	Size and Material		OVERHEAD TELECOMM LINES					
	Utility Conflict Description		LINES TO BE RELOCATED WITH POLE RELOCATION					
	Longitudinal or Crossing		LONGITUDINAL					
	Placement Relative to ROW		INSIDE					
LOCATION	Sheet No. 326							
	Station Origin							
	Start Station	658+36.74	End Station					
	Start Offset	9.61	End Offset					
	Latitude	29.398168271	Longitude	-98.4350532	212			
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
	Recommended Action		ACCOMODATE - RELOCATION					
RESOLUTION	Estimated Resolution Date							
	Resolution Status		UTILITY COORDINATION IN PROGRESS					
	Comment		RELOCATE LINES IN CONJUNCTION WITH POWER POLE RELOCATION, SEE CONFLICT ID 240 FOR POLE RELOCATION					
Date Collected 11/8/2017 3:56:50 PM Date Modified 11/30/2017 8:34:39 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800