



Pavement Report

GENERAL INFO	<p>ID 283</p> <p>Corridor BS 123B</p> <p>Latitude +29.584244</p> <p>Longitude -97.964847</p> <p>Google Maps Hyperlink <a +29.584244,-97.964847"="" href="http://local.google.com/maps?q=">http://local.google.com/maps?q="+29.584244,-97.964847</p> <p>Field Notes 4' wide strip of repair 54' long out from rail removal from center of road 2' wide strip of repair 66' long out from rail removal from shldr pvmk of road</p>
UTILITY DETAILS	<p>Utility Pavement Repair</p> <p>Owner TXDOT</p> <p>Type Vertical</p>
SITE PHOTOS	<div style="display: flex; justify-content: space-around; text-align: center;"> <div style="width: 30%;"> <p>Photo 1</p>  </div> <div style="width: 30%;"> <p>Photo 2</p>  </div> <div style="width: 30%;"> <p>Photo 3</p> </div> </div>
<p>Date Collected 11/8/2017 2:15:33 PM Date Modified 12/11/2017 12:12:38</p>	