

## Utility Conflict Report

|                       |                                     |                                  |                 |                       |                    |
|-----------------------|-------------------------------------|----------------------------------|-----------------|-----------------------|--------------------|
| <b>OWNER</b>          | <b>Utility</b>                      | AT&T                             | <b>Corridor</b> | SW MILITARY           | <b>SITE PHOTOS</b> |
|                       | <b>Contact</b>                      | PHILIP AUSTIN                    | <b>ID</b>       | 1063                  |                    |
| <b>GENERAL INFO</b>   | <b>Utility</b>                      | COMMUNICATIONS                   |                 |                       |                    |
|                       | <b>Size and Material</b>            | OVERHEAD TELECOMM LINES          |                 |                       |                    |
|                       | <b>Accessible Route</b>             | ASSET IS INSIDE ACCESSIBLE ROUTE |                 |                       |                    |
|                       | <b>Longitudinal or Crossing</b>     | LONGITUDINAL                     |                 |                       |                    |
|                       | <b>Placement Relative to ROW</b>    | INSIDE ROW                       |                 |                       |                    |
| <b>LOCATION</b>       | <b>Sheet No.</b>                    | 155                              |                 |                       |                    |
|                       | <b>Station</b>                      | 680+56.42                        |                 |                       |                    |
|                       | <b>Offset</b>                       | 17.22                            |                 |                       |                    |
|                       | <b>Latitude</b>                     | +29.356535                       |                 |                       |                    |
|                       | <b>Longitude</b>                    | -98.51317                        |                 |                       |                    |
| <b>SUE</b>            | <b>Level of Investigation Req'd</b> | NONE                             |                 |                       |                    |
|                       | <b>Test Hole No</b>                 | N/A                              |                 |                       |                    |
|                       | <b>Test Hole Depth</b>              | N/A                              |                 |                       |                    |
| <b>RESOLUTION</b>     | <b>Recommended Action</b>           | NO CONFLICT                      |                 |                       |                    |
|                       | <b>Estimated Resolution Date</b>    |                                  |                 |                       |                    |
|                       | <b>Resolution Status</b>            | NO RESOLUTION WAS REQUIRED       |                 |                       |                    |
|                       | <b>Comment</b>                      | Related to utility ID 4156       |                 |                       |                    |
| <b>Date Collected</b> |                                     | <b>Date Modified</b>             |                 | 12/18/2018 4:04:28 PM |                    |

