

Utility Conflict Report

_									
OWNER	Utility	tility CHARTER		Corridor	SW MILITA	.RY	SITE PHOTOS		
	Contact	FRANK CY	PRIAN	ID	1142				
GENERAL INFO	Utility		COMMUNICATIONS						
	Size and Material		OVERHEAD TELECOMM LINES						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE			
	Longitudinal or Crossing		LONGITUDINAL				The second second		
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 2	204							
	Station 9	10+70.06							
	Offset -	16.84							
	Latitude +	-29.356828							
	Longitude .	-98.51312					50		
SUE	Level of Investigation Req'd		NONE				B176		
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date						The state of the s		
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Related to utility ID 7059						
Date Collected				Date I	Modified	12/18/2	018 4:05:41 PM		