

Utility Conflict Report

IER.	Utility	CHARTER		Corridor	SW MILITA	RY	SITE PHOTOS
OWNER	Contact	FRANK CY	PRIAN	ID	1156		
GENERAL INFO	Utility		COMMUNICATIONS				The state of the s
	Size and Material		OVERHEAD TELECOMM LINES				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			ITE	
	Longitudinal or Crossing		LONGITUDINAL				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 2	211					\\ \
	Station 9	945+32.04					
	Offset -	17.76					\ \
	Latitude -	+29.356813					
	Longitude	-98.50228					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Related to utility ID 7039				
	Date Collected			Date I	Modified	12/18/20	018 4:05:34 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800