

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH	_	ID			4 1		
O	Contact	ANNFECTI		טו	3089				
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			ITE			
	Longitudinal or Crossing		CROSSING				5.5		
	Placement Relative to ROW		INSIDE ROW				Market and the second		
LOCATION	Sheet No.	121							
	Station 5	510+16.99							
	Offset	19.6977							
	Latitude -	+29.358808							
	Longitude	-98.56656							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A				TO THE RES		
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		8/14/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Back of curb to sewer manhole = 6'-4" Unable to open manhole						
	Date Collected 7/19/2018 9:12:20 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800