

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3095		T	
0							THE TANK	
GENERAL INFO	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE		
	Longitudinal or Crossing		CROSSING)		
	Placement Relative to ROW		INSIDE ROW				/不可能·文字·"。	
LOCATION	Sheet No. 1	Sheet No. 125						
	Station 5	517+37.93						
	Offset 2	21.3549				7.		
	Latitude +	-29.358549						
	Longitude	-98.56425						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/14/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED			<i>5</i> //		
	Comment		Back of curb to sewer manhole = 7'-6" Top of cone to surface = 11" Lid thickness = 1 1/2"					
Date Collected 7/19/2018 10:48:12 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800