

Utility Conflict Report

ER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	3110		
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER			+	
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			E	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	132					
	Station 5	544+90.94					
	Offset 1						
	Latitude -						
	Longitude -98.55565						
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		12/18/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 464717 Front of sidewalk to pole = 4'-4" Back of curb to front of sidewalk = 8'-6" Back of curb to pole = 3'-0" CATV Cable				
	Date Collected 7/24/2018 9:13:10 AM Date Modified 12/18/2018 3:56:50 PM						

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800