

## **Utility Conflict Report**

OWNER	Utility	SAWS		Corridor	SW MILITA	ARY	SITE PHOTO		
×  ×	Contact ANN PECH		E <b>ID</b>	ID	3115		NEW (ELIMATE		
0									
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	134							
	Station 5	546+36.55							
	Offset 2	21.43							
	Latitude -	+29.357736							
	Longitude	-98.55517							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ILITY			
	Comment		Top of valve to surface = 10" Lid thickness = 3/8" Sidewalk width = 4'-5" Front of sidewalk to valve = 6.5"						
	<b>Date Collected</b> 7/24/2018 9:52:09 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800